

# Solid Shift

Vehicle	Model	Engine	Part no.	Code	Price with tax	Price	Genuine NISSAN part no.
Silvia 180SX	S13, RS13	CA18DE, CA18DET	32839-RN540	A	16,800	16,000	32839-35F11 32839-35F12 32839-70F00 32839-70F01
	PS13, RPS13	SR20DE, SR20DET					
Silvia	S14	SR20DE, SR20DET	32839-RN540	A	16,800	16,000	32839-35F11 32839-35F12 32839-70F00 32839-70F01
	S15	SR20DE (except Autech Version)					
Skyline	R32(FR)	RB20E, RB20DE, RB20DET, RB25DE	32839-RN580	A	16,800	16,000	32839-71L00 32839-71L10
	HNR32(GTS-4)	RB20DET	32839-RN595	A	16,800	16,000	32839-05U01 32839-05U11
	BNR32(GT-R)	RB26DETT					
	HR33, E(C)R33	RB20E, RB25DE	32839-RN580	A	16,800	16,000	32839-71L00 32839-71L10
	ECR33	RB25DET	32839-RN590	A	16,800	16,000	32839-21U00
	ENR33(GTS-4)	RB25DE *Autech Version(4door) is set available	32839-RN595	A	16,800	16,000	32839-05U01 32839-05U11
	BCNR33(GT-R)	RB26DETT					
	R34(FR)	RB20DE, RB25DE, RB25DET	32839-RNR40	A	16,800	16,000	32839-AA500 32839-AB000 32839-05U11
ENR34(25GT FOUR)	RB25DE	32839-RN595					
Cefiro	(C)A31, E(C)A31	RB20E, RB20DE, RB20DET, RB25DE ※NA31(4WD) M/T is not apliciate	32839-RN580	A	16,800	16,000	32839-71L00 32839-71L10
Laurel	H(C)C33, SC33	RB20E, RB20DE, RD28 ※RB20DET, RB25DE M/T is not apliciate					
Stagea	WGNC34	RB26DETT(260RS), RB25DET(4WD)	32839-RN595	A	16,800	16,000	32839-05U11

## Features

By hardening the inner rubber of a standard shift lever, the amount of deflection is decreased. At the same time, the lever length was reduced by about 7.5mm, providing a stroke 10% shorter. This changes the rather soft touch of a standard car to a much more precise, fast feeling. At the same time, while the goal is to change to a quicker shift, an overly short shift stroke will result in poor, heavy shifting. Unlike a quick shift, the lever ratio has not been changed, so the transmission synchro is not effected and a moderately faster degree of shifting is possible. Installation is easy because the solid shift has the same basic dimensions as a standard shift.

## Product Note

- The NISMO Solid Shift is for use with manual transmission vehicles only.
- Install only in compatible vehicles. Failure to do so can result in being unable to shift, as well as damage to the shift collar and snap ring.
- Vehicles using the same genuine Nissan part number can in general use this part.

